

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401768193  
Date Received:  
09/19/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840  
Name of Operator: SCHNEIDER ENERGY SERVICES INC  
Address: P O BOX 889  
City: FORT MORGAN State: CO Zip: 80701  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Schneider, Jeff	970-867-9437	jeff@schneiderenergy.com
Bothwell, Kevin	970-867-9437	kbothwell@schneiderenergy.com
Pesicka, Conor		conor.pesicka@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 691200347  
Inspection Date: 08/17/2018 FIR Submit Date: 08/18/2018 FIR Status:

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC Company Number: 76840  
Address: P O BOX 889  
City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 306577

Location Name: DRYER-67N60W Number: 14NWNW County:  
Qtrqr: NWN Sec: 14 Twp: 7N Range: 60W Meridian: 6  
W  
Latitude: 40.580720 Longitude: -104.067110

FACILITY - API Number: 05-123-00 Facility ID: 306577

Facility Name: DRYER-67N60W Number: 14NWNW  
Qtrqr: NWN Sec: 14 Twp: 7N Range: 60W Meridian: 6  
W  
Latitude: 40.580720 Longitude: -104.067110

CORRECTIVE ACTIIONS:

1 CA# 117990

Corrective Action: Comply with Rule 210.e using the Rule 210.e guidance document for further details. Date: 10/19/2018  
Response: CA COMPLETED Date of Completion: 09/17/2018

Put hazard label on drum

Operator Comment: \_\_\_\_\_

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 117991

Corrective Action: Remediate stained equipment; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 09/19/2018

Response: CA COMPLETED

Date of Completion: 09/17/2018

Operator Comment: Washed of pumping unit gearbox

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 117992

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 09/19/2018

Response: CA COMPLETED

Date of Completion: 09/18/2018

Operator Comment: Hauled off damaged belt guard

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**4** CA# 117993

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 09/19/2018

Response: CA COMPLETED

Date of Completion: 09/18/2018

Operator Comment: Cleaned up stained soil

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**5** CA# 117994

Corrective Action: Plumb bradenhead to surface; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 09/19/2018

Response: CA COMPLETED

Date of Completion: 09/18/2018

Operator Comment: Pumped bradenhead to surface.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Bothwell

Signed: \_\_\_\_\_

Title: Employee

Date: 9/19/2018 1:51:07 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401768219	Photos of Dryer site
-----------	----------------------

Total Attach: 1 Files