

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401745452  
Date Received:  
08/27/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Recipient, Single		Inspections@catamountep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602788  
Inspection Date: 06/18/2018 FIR Submit Date: 07/04/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 333792

Location Name: JACQUES-N33N8W Number: 27SENW County: LA PLATA  
Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.076490 Longitude: -107.707860

### FACILITY - API Number: 05-067-00 Facility ID: 454865

Facility Name: Jaques Number: 9  
Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.076490 Longitude: -107.707860

### CORRECTIVE ACTIONS:

1 ☒ CA# 117190

Corrective Action: Stormwater controls such as silt traps and armoring are needed at culvert inlets and outlets to prevent erosion from stormwater flows along the access road. Check dams will likely be needed in roadside ditches. Stormwater controls are also needed on loose soils along roadside to prevent sediment runoff, and revegetation is needed on these soils for long term stabilization. Seeding is required by November 1, 2018 and remaining stormwater controls need to be installed by August 4, 2018.

Date: 08/04/2018

Response: CA COMPLETED Date of Completion: 08/03/2018

Installed silt traps, armored culverts, installed check dams along road side ditches. Retrenched waddles, cleaned and reset others, repaired and cleaned out diversion ditch, cleaned repaired and reinforced rock rundown in NE corner of location.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 8/27/2018 2:27:30 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401745452	FIR RESOLUTION SUBMITTED
401745456	Remedial Report

Total Attach: 2 Files