



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 075 - 08153		LEASE NAME: Henderson 2	
LOCATION: NWSE 24-8N-53W		OPERATOR: Monghan	
DATE: 6-30-98		INSPECTOR: Ed Binkley	
Insp. Type: SR	Insp. Status: PA	PA: <input checked="" type="checkbox"/> N	Pass/Fail: <input checked="" type="checkbox"/> F Viol.: Y <input checked="" type="checkbox"/> N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	Plugged 3-22-93	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	Cultivated	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:	
 00252005	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

AUG 14 1998