

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401693065  
Date Received:  
07/03/2018

FIR RESOLUTION FORM

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 33825  
Name of Operator: GEOTECH PRODUCTION INC  
Address: 7844 S ESPANA WAY  
City: AURORA State: CO Zip: 80016-1918  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
henderson, ralph (303) 690-0921 hap7844@aol.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689801158  
Inspection Date: 05/21/2018 FIR Submit Date: 05/30/2018 FIR Status:

Inspected Operator Information:

Company Name: GEOTECH PRODUCTION INC Company Number: 33825  
Address: 7844 S ESPANA WAY  
City: AURORA State: CO Zip: 80016-1918

LOCATION - Location ID: 312987

Location Name: SPETTER-68N90W Number: 8SWNW County: MOFFAT  
Qtrqr: SWN Sec: 8 Twp: 8N Range: 90W Meridian: 6  
W  
Latitude: 40.669060 Longitude: -107.522790

FACILITY - API Number: 05-081-00 Facility ID: 223186

Facility Name: SPETTER Number: 5-8  
Qtrqr: SWN Sec: 8 Twp: 8N Range: 90W Meridian: 6  
W  
Latitude: 40.669060 Longitude: -107.522790

CORRECTIVE ACTIIONS:

1  CA# 116585

Corrective Action: Comply with Rule 603.f . Date: 05/31/2018

Response: CA COMPLETED Date of Completion: 06/19/2018

Operator Comment: All risers and lines were bull plugged last fall. Someone recently STOLE all of the plugs and caps. They have now been replaced. When tank is removed from the lease (see latter comments) the risers will be removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

2  CA# 116586

Corrective Action: Comply with Rule 603.f .

Date: 08/30/2018

Response: CA COMPLETED

Date of Completion: 09/12/2018

Operator Comment: A sale of the tank is still pending, but complicated by ownership issues. Operator thinks tank is his, Black Hills Marketing (owner of separator facility) also claims ownership. This issue recently came to light as we were closing the sale, with plans to remove the tanks during dry weather. Regardless, the tank will be removed this summer.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

3  CA# 116587

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/02/2018

Response: CA COMPLETED

Date of Completion: 06/19/2018

Operator Comment: Waddles have been replaced and re-staked and properly anchored.  
The well pad area has been sprayed with weed control with blue marker.  
Additionally, Alan Pontaine, TCO (970-216-9119) is our field supervisor. Please feel free to contact him directly should the need arise.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Alan Pontaine with TCO (970-216-9119) is our field superintendent. Please feel free to contact him should the need arise.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ralph Henderson

Signed: \_\_\_\_\_

Title: President

Date: 7/3/2018 12:30:10 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401693065	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files