

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT 1
(Other side)
00244928Approved
Bureau No. 42-R1424
SECTION AND SERIAL NO.

C-10584

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

5. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Talamantes

8. FARM OR LEASE NAME

Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

17, 11N-100W

12. COUNTY OR PARISH

Moffat

13. STATE

Colo.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

534-0677

JUL 2 1976

2. NAME OF OPERATOR

Samedan Oil Corporation

COLO. OIL & GAS CONS. COMM.

3. ADDRESS OF OPERATOR

633 17th Street-Suite 1280 Denver, Colo. 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

580' FNL & 700' FEL. of section.

14. PERMIT NO. 76-544

03 081 6288

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion or Well
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spud on 5-31-76. Drilled 37 ft. surface hole and set 36 Ft. of 30 inch conductor pipe and cemented to surface. Drilled to 51 ft. and lost all returns, attempted to cement off lost circulation zone with 300 sx. common cement and failed. Began to drill without return. Reached 152 ft. and ground under and around rig began to sink badly. Plan to move rig approx. 350 ft. south and drill new hole. Will fill in old reserve pits level and clean up old pad. Will survey new location and run elevation.

DVR

FJP

HHM

JAM

JJD

GCH

CGM

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

DIRECTOR

O & G CONS. COMM.

DATE

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: