

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2018

Submitted Date:

09/28/2018

Document Number:

689701837**FIELD INSPECTION FORM**Loc ID 335597 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	
Hogelin, Thomas		thogelin@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
White, Brent	970-285-2200	bwhite@bry.com	Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285014	WELL	PR	09/24/2013	GW	045-12349	CHEVRON 5-3D	PR
285015	WELL	PR	07/25/2007	GW	045-12350	CHEVRON 5-1D	PR
285016	WELL	PR	01/12/2010	GW	045-12343	CHEVRON 5-2D	PR
285041	WELL	PR	07/25/2007	GW	045-12352	CHEVRON 5-4D	PR

General Comment:

Routine General Field Inspection

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Label on 100 bbl tank is peeling, cracking, and discoloring.		
Corrective Action:	Comply with Rule 210.e.	Date:	11/30/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2200

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:	Deadmen are not marked.		
Corrective Action:	Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q.	Date:	10/15/2018
Type: Horizontal Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	285014	Type:	WELL	API Number:	045-12349	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285015	Type:	WELL	API Number:	045-12350	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285016	Type:	WELL	API Number:	045-12343	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285041	Type:	WELL	API Number:	045-12352	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Ditches	Pass			
Ditches	Pass					
Gravel	Pass					
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Fail					Land farm berm
Compaction	Pass					

Comment: [Land farm berm is using location berm for back berm wall. Land farm material piled over on top of location berm.](#)

Corrective Action: [Repair required BMPs per Rule 1002.f.](#)

Date: 10/05/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701838	Inspection 689701837 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593733