

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401783208
Date Received:
10/03/2018

FIR RESOLUTION FORM

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

Ray, Mandi

505-324-5122

mray@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685305320

Inspection Date: 09/06/2018

FIR Submit Date: 09/07/2018

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325466

Location Name: TIFFANY 2 Number: 3 County: LA PLATA

Qtrqtr: SESE Sec: 2 Twp: 32N Range: 7W Meridian: N

Latitude: 37.042010 Longitude: -107.573250

FACILITY - API Number: 05-067- -00 Facility ID: 419641

Facility Name: TIFFANY 2 Number: 3

Qtrqtr: SESE Sec: 2 Twp: 32N Range: 7W Meridian: N

Latitude: 37.042010 Longitude: -107.573250

CORRECTIVE ACTIONS:

1 ☒ CA# 118512

Corrective Action: Comply with Rule 603.f.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 09/27/2018

Operator Comment: Unused risers removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 118513

Corrective Action: Clean up impacted soil and properly dispose of impacted soil and gravel to comply with Rule 907.e.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 09/27/2018

Operator
Comment:

Impacted soil cleaned up and properly disposed of. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 118514

Corrective Action: Clean up and properly dispose of impacted soil and gravel to comply with Rule 907.e.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 09/27/2018

Operator
Comment:

Impacted soil cleaned up and properly disposed of. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 118515

Corrective Action: Install or remove unused equipment to comply with Rule 603.f.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 09/26/2018

Operator
Comment:

Drip pans, guard panel and steel rod at wellhead removed. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 ☒ CA# 118516

Corrective Action: Remove thistle and implement weed management to comply with Rule 1003.f.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator
Comment:

The thistles have been removed and treated. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 10/3/2018 2:54:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401783208	FIR RESOLUTION SUBMITTED
401783244	Tiffany 2-3 Resolution Photos 685305320

Total Attach: 2 Files