

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401796576

Date Received:

10/15/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Knudson, Dwayne

(970) 456-3335

dknudson@ursaresources.com

Pesicka, Conor

conor.pesicka@state.co.us

Holtz, Darin

darin.holtz@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680200178

Inspection Date: 10/10/2018

FIR Submit Date: 10/10/2018

FIR Status: _____

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 1600 BROADWAY ST STE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 419380

Location Name: Diemoz Number: A Pad County: _____

Qtrqr: NWS Sec: 36 Twp: 5S Range: 92W Meridian: 6

Latitude: 39.569521 Longitude: -107.671988

FACILITY - API Number: 05-045- -00 Facility ID: 419380

Facility Name: Diemoz Number: A Pad

Qtrqr: NWS Sec: 36 Twp: 5S Range: 92W Meridian: 6

Latitude: 39.569521 Longitude: -107.671988

CORRECTIVE ACTIONS:

2 CA# 119433

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/01/2018

Response: CA COMPLETED

Date of Completion: 10/12/2018

Additional sign was installed to add language so the wellhead sign covered the information required to go on the tank battery in its absence. See photo

Operator _____
Comment: _____

COGCC Decision: _____

COGCC Representative: _____

3 CA# 119434

Corrective Action: Install sign to comply with Rule 210.b. Date: 10/01/2018

Response: CA COMPLETED Date of Completion: 10/12/2018

Operator Comment: Additional sign was installed to add language so the wellhead sign covered the information required to go on the tank battery in its absence. See photo

COGCC Decision: _____

COGCC Representative: _____

4 CA# 119435

Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 10/12/2018

Response: CA COMPLETED Date of Completion: 10/12/2018

Operator Comment: BMPs installed at discharge end of farmer's discharge drainage. See Photos

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Shaun Kellerby

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson Signed: _____

Title: Environmental Manager Date: 10/15/2018 12:59:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401796583	SW Installation Photo
401796584	SW Installation Photo
401796585	Signage Photo

Total Attach: 3 Files