

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2018

Submitted Date:

11/01/2018

Document Number:

679300008**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Graber, Candice (Nikki) 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Bob		robert.chesson@state.co.us	
Axelson, John		john.axelson@state.co.us	
,		cogccinspection@pdce.com	ALL INSPECTIONS
Oakman, Kari		kari.oakman@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449950	LAND APPLICATION SITE	AC	05/23/2017		-	Becker Ranch #2 LA Area 449950	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.  
 Photos attached to document site condition at the time of inspection.  
 Corrective actions identified that require 24 hour response from operator.

**Location****Lease Road:**

Type	Access		
comment:	Tracking pad not installed or not adequately maintained to prevent track of material offsite. Material is being transported onto county road to south.		
Corrective Action:	Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f. (2)F. Material is tracked onto County or public roads, contact the appropriate authority.	Date:	11/01/2018

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	449950	Type:	LAND	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: DRILLING FLUIDS

Estimated Spill Volume: \_\_\_\_\_

Comment: Material is being transported offsite by vehical tracking (photos 3 &amp; 4).

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. See attached photos of areas where material was observed off location. Report in accordance with Rule 906.b.

Date: 11/01/2018

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

Drill Cuttings Land Application Inadequate \_\_\_\_\_

Comment: A significant amount of material is being stockpiled on site without incorporation.

Corrective Action: Perform land application in accordance with Rule 907.d.(3)B.

Date: 11/01/2018

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Fail			Material is being tracked

Comment: [Vehicle tracking reaching county road to west of the facility.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/01/2018

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679300011	Site Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4629888">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4629888</a>