

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401544080

Date Received:

02/14/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

1 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Ken Wonstolen

Phone

303-312-8170

Email

kwonstolen@billbarrettcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 677400507

Inspection Date: 02/08/2018

FIR Submit Date: 02/08/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BARRETT CORPORATION* BILL

Company Number: 10071

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332177

Location Name: GILLYIN-61N64W Number: 24NWNE County: _____

Qtrqtr: NWNE Sec: 24 Twp: 1N Range: 64W Meridian: 6

Latitude: 40.042370 Longitude: -104.496510

FACILITY - API Number: 05-123-00 Facility ID: 332177

Facility Name: GILLYIN-61N64W Number: 24NWNE

Qtrqtr: NWNE Sec: 24 Twp: 1N Range: 64W Meridian: 6

Latitude: 40.042370 Longitude: -104.496510

CORRECTIVE ACTIONS:

1 CA# 114371

Corrective Action: Repair and paint tanks per Rule 804.

Date: 06/08/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: Rule 804 states: "Production facilities, regardless of construction date, which are observable from any public highway shall be painted with uniform, non-contrasting, non-reflective color tones (similar to the Munsell Soil Color Coding System), and with colors matched to but slightly darker than the surrounding landscape." Bill Barrett Corporation personnel have verified these tanks are not visible from Hwy 52 to the north and Hwy 79 to the east, therefore the 804 rule does not apply.

COGCC Decision: **Not Approved**

COGCC Representative: Tank is visible from County Road 8.
-Conor Pesicka

COGCC Supervisor: Tank is visible from County Road 8.
-Conor Pesicka

2 ☒ CA# 114372

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 03/08/2018

Response: CA COMPLETED

Date of Completion: 03/08/2018

Operator Comment: In progress.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed: _____

Title: Sr. Permit Analyst

Date: 2/14/2018 3:56:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401544080	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files