

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401833944

Date Received:
11/09/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Rocky, TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689302204
Inspection Date: 10/26/2018 FIR Submit Date: 11/01/2018 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 439173

Location Name: Youberg RU Number: 44-7 County: GARFIELD
Qtrqr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.454779 Longitude: -107.810808

FACILITY - API Number: 05-045-00 Facility ID: 439166

Facility Name: Youberg RU Number: 444-7
Qtrqr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.454779 Longitude: -107.810808

CORRECTIVE ACTIONS:

1 CA# 120090

Corrective Action: If spilled, released or dumped onto ground surface follow material handling and guidance per MSDS or product data sheet. Submit document, procedures and waste disposal manifest to COGCC field inspector.

Date: 10/08/2018

Response: CA COMPLETED Date of Completion: 11/05/2018

Operator Comment: The frac sand shown in the inspection report is clean sand ... it has never been down hole and is not an E&P waste material. During a recent storm, some sand was blown out of the storage containers and accumulated around site equipment and perimeter fence. A hydro-vac truck was used to clean up the majority of the wind-blown sand, and only small traces / quantities of the innocuous, inert, clean sand remain on site. The sand is clean, pure, silica sand and is an abundant naturally occurring mineral and poses no environmental hazard.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: TEP has used a vac-truck to cleanup as much of the wind-blown, clean sand as possible. Only trace amounts of this inert, natural material remain on site.

The guidance for managing this material as provided in the MSDS sheet has been followed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 11/9/2018 10:21:49 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files