

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401823457

Date Received:

11/02/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Zack Liesenfeld		zack.liesenfeld@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689500873

Inspection Date: 10/31/2018

FIR Submit Date: 11/01/2018

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 329819

Location Name: HSR-CULLEN ODENBAUGH-63N67W Number: 12NESW County: _____

Qtrqtr: NESW Sec: 12 Twp: 3N Range: 67W Meridian: 6

Latitude: 40.238044 Longitude: -104.841308

FACILITY - API Number: 05-123-00 Facility ID: 448329

Facility Name: MSW #1 Number: _____

Qtrqtr: NESW Sec: 12 Twp: 3N Range: 67W Meridian: 6

Latitude: 40.238044 Longitude: -104.841308

CORRECTIVE ACTIIONS:

1 CA# 120107

Corrective Action: Immediately stop tracking E&P Waste off location. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. Material is tracked onto County or public roads, contact the appropriate authority.

Date: 11/01/2018

Response: CA COMPLETED Date of Completion: 11/02/2018

Operator Comment: Material transported off site will be stopped and addressed. Vehicle tracking BMP's will comply with rule 1002.f.(2)F.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo's provided show the facility has been temporarily closed and the access road issues addressed.

2 CA# 120108

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. See attached photos of areas where material was observed off location. Report in accordance with Rule 906.b. Date: 11/01/2018

Response: CA COMPLETED Date of Completion: 11/02/2018

Operator Comment: Bentonitic material transported off site will be addressed. Reporting in accordance with Rule 906.b. will be conducted if material is thought to be over reporting thresholds.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo's provided show the facility has been temporarily closed and the access road issues addressed.

3 CA# 120109

Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 11/30/2018

Response: CA COMPLETED Date of Completion: 11/02/2018

Operator Comment: No evidence of southern berm erosion in photo. Please clarify.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zack Liesenfeld Signed: _____

Title: EHS Rep Date: 11/2/2018 3:23:19 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401823457	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files