

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Battery sign.

**Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070**



Sign has paint over spray.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



No capacity volume on tank label.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Riling

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Sediment build up in ditch behind separators.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Movement of sediment and collecting at separators.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Movement of sediment and collecting at separators.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Washing around tank berm.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Washing and riling of sediment trap.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Ditch is rutted.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Junk and trash at well.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Absorbent spill pads inside of hole next to the cellar of well GM 706-4-HN2.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Unmarked deadman



Unmarked deadman

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Unmarked deadman



Unmarked deadman

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Junk




Junk

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070




Washing and riling along shoulder above culvert.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Rutted road and ditch unmaintained.

Federal MV-28-4
Api # 05-045-06787
Inspection # 689702070



Rutted road and ditch unmaintained.