

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401788870

Date Received:

10/09/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tammy Fredrickson

307-352-7514

Tammy.Fredrickson@dominionenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400182

Inspection Date: 09/26/2018

FIR Submit Date: 10/03/2018

FIR Status: _____

Inspected Operator Information:

Company Name: WEXPRO COMPANY

Company Number: 95960

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

LOCATION - Location ID: 313126

Location Name: CHAPMAN STATE-611N97W Number: 16NESE County: MOFFAT

Qtrqr: NESE Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.911740 Longitude: -108.289720

FACILITY - API Number: 05-081- -00 Facility ID: 223608

Facility Name: CHAPMAN STATE Number: 1

Qtrqr: NESE Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.911740 Longitude: -108.289720

CORRECTIVE ACTIONS:

1 ☒ CA# 119231

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 10/08/2018

Response: CA COMPLETED

Date of Completion: 10/04/2018

Operator Comment: Spill was cleaned up per direction from Kris Neidel.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 119232

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/08/2018

Response: CA COMPLETED

Date of Completion: 10/04/2018

Operator Comment: All equipment has been disconnected and is out of service. Spill material came for the removal of a dehy. When dehy was moved, old crude oil deposit was spilled on the ground without the knowledge of the contractor moving the piece of equipment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: At the direction of Kris Neidel on 10/4/18 at 10:13 AM, spill was cleaned up by removing contaminated soil and hauling it to the Rock Springs landfill. Disposal ticket is attached. Spill material (crude oil) was sludge and weathered and posed no risk of mobility. Spill was below reportable levels and and at the direction of Kris Neidel, Wexpro is requesting closure of the incident.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Fredrickson

Signed:

Title: Senior Permit Agent

Date: 10/9/2018 10:19:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

401788870	FIR RESOLUTION SUBMITTED
401788898	Trucking
401788907	Photos

Total Attach: 3 Files