

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401850519

Date Received:  
11/26/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lorne C Prescott

970 812 5311

lprescott@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 681701117

Inspection Date: 11/01/2018

FIR Submit Date: 11/02/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324288

Location Name: CC Number: 0616-21-32 County: \_\_\_\_\_  
Pad

Qtrqtr: SENW Sec: 16 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.525690 Longitude: -108.228311

FACILITY - API Number: 05-045- -00 Facility ID: 324288

Facility Name: CC Number: 0616-21-32  
Pad

Qtrqtr: SENW Sec: 16 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.525690 Longitude: -108.228311

CORRECTIVE ACTIONS:

1 CA# 120128

Corrective Action: Contact COGCC EPS Steven Arauza to discuss liner repair and tears in liner along anchor trench.

Date: 11/09/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator  
Comment: Done

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 120129

Corrective Action: Elevate hose with hammer union to prevent direct contact with pit liner. Repair or replace ratchet strap to prevent contact with pit fluids.

Date: 12/02/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator  
Comment:

Done

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 120130

Corrective Action: Submit a Form 4 Sundry notice to provide documentation of netting agreement with CPW. Repair holes in pit fence to prevent access, per Rule 902.d.

Date: 11/09/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator  
Comment:

Letter from CPW received. See attached

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 120131

Corrective Action: Remove oil from pit per Rule 902.c. within 24 hours of COGCC notification.

Date: 11/02/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator  
Comment:

Done, oil sheen was barely detectable.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: \_\_\_\_\_

Title: Reg & Enviro Compliance

Date: 11/26/2018 3:58:00 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401850535	CPW Bird Netting Email

Total Attach: 1 Files