

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2018

Submitted Date:

12/06/2018

Document Number:

690300389**FIELD INSPECTION FORM**Loc ID 315051 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arauzo, Steven		steven.arauza@state.co.us	
Trujillo, Helen		notices@rlbayless.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

Site inspection to assess pit closure/remediation. Temp 26F, cloudy, 3-4 inches snow cover. Pit is at south side of pad, remains open and has been overexcavated to ~ 4'bgs. ~ 5-10 cy soil stockpiled on west side. No visual or olfactory evidence of petro contamination in pit or stockpile. Well P&A completed at north side of pad.. Wellhead cutoff 4'bgs and cutoff pipe laying on surface. Flowline riser remains in place but excavated to ~4 'bgs at SE corner. Four deadmen remain in place at four corners of pad.

Complete remediation and closure per REM12018 plan and COA. Complete reclamation per BLM requirements.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300391	Insp photos 11/27/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4667315