

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2018

Submitted Date:

12/17/2018

Document Number:

688400900**FIELD INSPECTION FORM**Loc ID 320022 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202290	WELL	SI	01/01/2017	GW	001-07695	HACK 12-14	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 202290 Type: WELL API Number: 001-07695 Status: SI Insp. Status: SI

**Workover**

Comment: At time of inspection workover rig was performing a MIT. MIT failed Operating company in contact with engineering department.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
Operating company performing a MIT at time of inspection. MIT failed operator is in contact with engineering department on how to proceed forward. At time of inspectio spoke with Extraction reps and land owner. Land owner had concerns with time frame of rig being on site. Extraction told land owner they will try to be completed by FRI 12/21/2018.	silverr	12/17/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400901	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679787">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679787</a>