

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2018

Submitted Date:

12/12/2018

Document Number:

679702123**FIELD INSPECTION FORM**

Loc ID 315564 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Foundation		regulatory@foundationenergy.com	Regulatory
Waldron, Emily		emily.waldron@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231050	WELL	PR	05/01/2017	GW	103-08719	RANGELY SOUTH FED 4-1-102	PR

General Comment:

routine well inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers 2 containers without labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/15/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery Missing nearest public road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/15/2019
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers 112 bbl tank missing capacity sign.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/15/2019
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery Sign is missing.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/15/2019

Emergency Contact Number:

Comment: 866-767-3600

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	STEEL AST		39.985370,-108.796970	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	112 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 231050	Type: WELL	API Number: 103-08719	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing well			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401872699	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674347
679702124	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4674340