

**STATE OF
COLORADO****Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>**

Petroshare Double J 35-11 Pad doc no 401445455

4 messages

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>

Thu, Dec 7, 2017 at 3:27 PM

To: Christi Ng <cng@progressivepcs.net>

Christi,

COGCC is in the process of reviewing the Form 2A for the Petroshare Double J 35-11 Pad (doc no 401445455). In order for us to complete our review, please address the following:

1. Please confirm that four separators is enough for 12 wells.
2. Under the water resources, based on the distance to surface water and water well, the area should be sensitive. With your concurrence, I will change the designation to Yes for sensitive area.
3. Please confirm the nearest water well. Based on the Division of Water Resources water well permit database, the nearest water well is permit 133-WCB/ Receipt C620133 at approximately 390 feet northwest of the reference point. This water well is not represented on the Location Drawing. Please confirm the presence of the water well and clarify either on the map or on the 2A.
4. Under the comments section, please provide further explanation of the comments "Borrow Ditch located SW of location, not visible in field at time of survey." Was there not water in the ditch? Has the ditch been filled in and plowed over?
5. The first BMP listed is in regards to hot work permits, which is an Operator comment and not an enforceable BMP. Please inform COGCC if this should be moved to the comments section or removed from the 2A.

Please let me know if you have questions or would like to further discuss any of the above.

Thank you,

Rebecca

--

Rebecca Treitz
Oil and Gas Location Assessment Specialist
P 303.894.2100 x5173 | F 303.894.2109 |
1120 Lincoln Street, Suite 801, Denver, CO 80203
Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

Christi Ng <cng@progressivepcs.net>

Mon, Dec 11, 2017 at 3:23 PM

To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>

Cc: Meghan Grimes <mgrimes@petrosharecorp.com>

Hi Rebecca,

Thank you for reviewing the form. Please see my comments below.

Christi

From: Treitz - DNR, Rebecca [mailto:rebecca.treitz@state.co.us]
Sent: Thursday, December 7, 2017 3:28 PM
To: Christi Ng <cng@progressivepcs.net>
Subject: Petroshare Double J 35-11 Pad doc no 401445455

Christi,

COGCC is in the process of reviewing the Form 2A for the Petroshare Double J 35-11 Pad (doc no 401445455). In order for us to complete our review, please address the following:

1. Please confirm that four separators is enough for 12 wells. [PetroShare](#) is reviewing with their production team.
2. Under the water resources, based on the distance to surface water and water well, the area should be sensitive. With your concurrence, I will change the designation to Yes for sensitive area. [Yes please](#).
3. Please confirm the nearest water well. Based on the Division of Water Resources water well permit database, the nearest water well is permit 133-WCB/ Receipt C620133 at approximately 390 feet northwest of the reference point. This water well is not represented on the Location Drawing. Please confirm the presence of the water well and clarify either on the map or on the 2A. [Yes, please add: The nearest water well is permit 133-WCB/Receipt C620133 at approximately 360' NW of the reference point.](#)
4. Under the comments section, please provide further explanation of the comments "Borrow Ditch located SW of location, not visible in field at time of survey." Was there not water in the ditch? Has the ditch been filled in and plowed over? [At the time of survey, the ditch did not have water.](#)
5. The first BMP listed is in regards to hot work permits, which is an Operator comment and not an enforceable BMP. Please inform COGCC if this should be moved to the comments section or removed from the 2A. [Please remove.](#)

[Please let me know if you have questions or would like to further discuss any of the above.](#)

Thank you,

Rebecca

--

Rebecca Treitz

Oil and Gas Location Assessment Specialist

P 303.894.2100 x5173 | F 303.894.2109 |

[1120 Lincoln Street, Suite 801, Denver, CO 80203](#)

Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>
To: Christi Ng <cng@progressivepcs.net>

Fri, Jan 26, 2018 at 6:30 PM

Thanks Christi,
I was wondering if there was any word on the equipment count?

Rebecca
[Quoted text hidden]

Christi Ng <cng@progressivepcs.net>
To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>

Sun, Jan 28, 2018 at 1:33 PM

Hi Rebecca,

I'm so sorry that I didn't get back to you on the equipment count- I spoke with their production manager as soon as I got this from you. He said the equipment list is accurate and there is enough planned equipment for the expected production, so no changes there.

Thanks,

Christi

From: Treitz - DNR, Rebecca [mailto:rebecca.treitz@state.co.us]

Sent: Friday, January 26, 2018 6:30 PM

To: Christi Ng <cng@progressivepcs.net>

Subject: Re: Petroshare Double J 35-11 Pad doc no 401445455

[Quoted text hidden]