

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401886890

Date Received:

12/27/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Jeff@schneiderenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404240
Inspection Date: 11/28/2018 FIR Submit Date: 12/04/2018 FIR Status:

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC Company Number: 76840
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 320521

Location Name: RUBY Number: 1 County:
Qtrqtr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6
Latitude: 39.973650 Longitude: -104.946970

FACILITY - API Number: 05-001-00 Facility ID: 320521

Facility Name: RUBY Number: 1
Qtrqtr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6
Latitude: 39.973650 Longitude: -104.946970

CORRECTIVE ACTIONS:

1 CA# 120761

Corrective Action: Comply with Rule 1003. Corrective action date is being back dated to when interim reclamation should have been performed. Date: 03/28/2018

Response: CA COMPLETED Date of Completion: 12/27/2018

Operator Comment: Visited location yesterday and pad is in process of being reclaimed. Dump trucks are running, dirt is being moved and a good part of the pad has already been reclaimed.

COGCC Decision: Not Approved

This is an acknowledgement that the document was received. COGCC Staff appreciates the update but is unable

COGCC Representative: to approve this resolution as "Corrective Action Complete" because this is only documenting reclamation progress. Once Interim Reclamation activities have been completed and stormwater erosion has been repaired, please notify COGCC Staff at that point. In the future, if an Operator wants to document progress on a corrective action, then submit a Form 4 Sundry Notice. The FIRR Form was intended to alert the inspector when corrective actions have been completed.

2 CA# 120762

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/01/2019

Response: CA COMPLETED

Date of Completion: 12/27/2018

Operator Comment: Visited pad yesterday and pad is in the process of being reclaimed. Equipment is on site and working to finish. Much of the pad has already been reclaimed from a dirt work perspective.

COGCC Decision: **Not Approved**

COGCC Representative: This is an acknowledgement that the document was received. COGCC Staff appreciates the update but is unable to approve this resolution as "Corrective Action Complete" because this is only documenting reclamation progress. Once Interim Reclamation activities have been completed and stormwater erosion has been repaired, please notify COGCC Staff at that point. In the future, if an Operator wants to document progress on a corrective action, then submit a Form 4 Sundry Notice. The FIRR Form was intended to alert the inspector when corrective actions have been completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Pad reclamation is in progress

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Bothwell

Signed: _____

Title: Manager

Date: 12/27/2018 9:19:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401886890	FIR RESOLUTION SUBMITTED
401886893	Pad Reclamation progress
401886894	Pad reclamation progress II
401886895	Pad reclamation progress III

Total Attach: 4 Files