

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2018

Submitted Date:

01/04/2019

Document Number:

680603466

**FIELD INSPECTION FORM**

Loc ID 333989 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	<a href="#">All SW Inspections</a>
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293872	WELL	PR	02/01/2011	GW	067-09460	BALLANTINE 34-9 32-4A	RI

**General Comment:**

[This is an interim reclamation and stormwater inspection.](#)

**Inspected Facilities**

Facility ID: 293872 Type: WELL API Number: 067-09460 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by pinyon juniper woodland and irrigated crop field. Revegetation is progressing within portions of the interim reclamation area, but also weedy in other portions, although largely dormant due to winter growing conditions.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action  Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action  Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_



Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680603467	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694300">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694300</a>