

PA 1-32  
API# 05-045-06849  
Inspection # 689702378



Well sign.  
Dead weeds.

PA 1-32  
API# 05-045-06849  
Inspection # 689702378



**Dead weeds around well and battery.**

PA 1-32  
API# 05-045-06849  
Inspection # 689702378



**Dead weeds around well and battery.**