

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2019

Submitted Date:

01/09/2019

Document Number:

678302381**FIELD INSPECTION FORM**

Loc ID 336455 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	Eng'g Project Mgr

General Comment:

equipment and general conditions as in previous inspection 690002966 of 4January 2019
stained soils near fire site observed in this inspection

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Separator	<= 1 bbl		
Comment: see attached photo of stained soils at north end of separator				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	02/08/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678302382	stained soils	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698579