



NOV 20 1958

(SUBM)



99999999

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.Office DenverLease No. 033622-AUnit G. D. Parkinson
(Iles Dome)

OIL & GAS

CONSERVATION COMMISSION

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
BEST IMAGE AVAILABLE

November 14, 1958

Well No. 35M is located 400 ft. from SW line and 700 ft. from E line of sec. 22
SE NE Sec 22 4N 92W 6th
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Iles Dome Moffat Colorado
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6397 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was plugged and abandoned in the following manner:

Placed 12 sack cement plug 3153' to 3096'

Shot 7" casing off at 2796' unable to pull casing.

Shot 7" casing off at 2700' and pulled casing.

Set 10 sack cement plug at bottom of surface casing, set 10 sack cement plug at surface and erected 4" marker in accordance with regulations.

AJJ	
DYR	
WRS	
HHM	
JAM	
FJP	
JJD	<input checked="" type="checkbox"/>
FILE	

TD
3483
Comp. 1935 - Entrada
re-comp. 1939 - Morr.

Oil exhausted Prod. - Probably re-entered

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum CorporationAddress Buff, 2810428**081-40011**

00684010

By J. G. WilkinsTitle Field Superintendent