

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	LOCATION		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	STAINED SOIL IN MULTIPLE SPOTS AROUND ENGINE SKID. SEE LOC PICS		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e		Date: <u>02/15/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	THREE UNMARKED WITH NO LOTO RISERS INSIDE SEPERATOR HOUSE TWO UNMARKED WITH NO LOTO RISERS TO THE WEST OF SEPERATOR HOUSE.		
Corrective Action:	Comply with Rule 603.f . 24 HOURS TO LOTO RISERS		Date: <u>02/15/2019</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 217413 Type: WELL API Number: 071-06190 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401908040	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706220
695100005	LOC PICS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706196