

Stout 9-4  
NESE Sec. 4-T5N-R65W  
Weld County, Colorado  
Daily Drilling Report (Cont'd)

4/13/93	MIRU #7 (Randy) to prep for re-frac.
4/14/93	Killed well w/2% KCl; RIH w/MS, 7 slim jts, & 2 3/8" work string; SDF high wind.
4/15/93	Fin RIH w/work string; Tagged sd @ 6975'; Washed out to PBTD @ 7090'; Rolled hole clean w/2% KCl; POOH & LD work string; SDF rig repair.
4/16/93	Loaded hole w/8 BW; Fin POOH & LD work string; Rig broke dn for part of day.
4/17/93	Press tested Niobrara perms w/BJ pump truck; Niobrara perms taking 1 BPM @ 3800#, 1.5 BPM @ 4000#, & 2 BPM @ 4500#; ISIP 4250#; 30 sec 3750#; 5 min 3000#; RIH w/fishing tool to rec press plug; No luck fishing; RIH w/diff fishing tool; Fishing tool broke - lost piece of metal on top of plug; SDF weekend.
4/18-19/93	SDF weekend.
4/20/93	RIH w/3 1/2" magnet to attempt to fish piece of steel; Made 3 unsuccessful runs; RIH w/plunger fishing tool - unsuccessful; SD; WO fishing tool.
4/21/93	RIH w/finger basket on 2 3/8" tbg; Circ top of fish clean; SDFN.
4/22/93	Broke circ; POOH w/finger basket; RIH w/overshot; Tried to fish plug; POOH - no fish; Started IH w/cmt dump bailer; Well started flowing; POOH; Let well flow over night.
4/23/93	Flowed 28 BO overnight; Killed well w/2% KCl; Start RIH w/3 3/4" cone bit; Well kicked off flowing; Tried to kill - Tri-plex pump broke dn; WO new pump; Fin RIH; Started drlg; Circ up chunks of alum, piece of steel, & alum shavings from plug; SDFN.
4/24/93	Started drlg again; Fin drlg thru plug & frac ring; Ran to PBTD @ 7090'; Circ clean; POOH & LD tbg; SDF weekend.
4/26/93	RD & MO this am.
4/27-29/93	WOCU.
4/30/93	RU Goodwell; RU 4 1/2" lubricator; Re-perf'd Codell from 7010' - 7020' 4 spf w/2 1/2" RTG (orig perms were from 7006' - 7020' w/bi-wire gun); RD Goodwell.