

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2019

Submitted Date:

02/01/2019

Document Number:

682504477

FIELD INSPECTION FORM

Loc ID 303100 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 44350
Name of Operator: J W OPERATING COMPANY
Address: 15505 WRIGHT BROTHERS DRIVE
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------|---------|
| | | jwalker@milmen.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 252457 | WELL | DM | 11/08/1991 | GW | 125-06331 | KELLER CATTLE CO 10-13 | RI |

General Comment:

This inspection is being submitted in regards to active Rosewood Resources equipment on JW Operating's Keller Cattle Co #10-13 location #303100.

The Keller Cattle #10-13 well has been plugged and abandoned, it has been determinend that the remaining flowlines and metering equipment on this location are associated with two (2) active wells operated by Rosewood Resources Inc. As Rosewood is the last operator with active wells associated to this location and metering equipment, COGCC staff has determined that Rosewood Resources and JW Operating will need to collaborate and submit a Form 10 to change ownership/management of the Keller Cattle Co Location #303100 to Rosewood Resources.

PLEASE SEE COMMENT AND CORRECTIVE ACTION BELOW, AND UNDER "COGCC COMMENTS", REGARDING SUBMISSION OF THE FORM 10.

COMMENT:

Collaborate with ROSEWOOD RESOURCES INC #75027 to submit the Form 10 to transfer ownership/management of the Keller Cattle Co Location #303100 to ROSEWOOD RESOURCES INC #75027

CORRECTIVE ACTION DATE

Submit Form 10 by 2/08/2019.

Inspected Facilities

Facility ID: 252457 Type: WELL API Number: 125-06331 Status: DM Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

| | |
|---|--|
| Corrective Action: <input style="width: 95%;" type="text"/> | Date <input style="width: 95%;" type="text"/> |
| Overall Final Reclamation <input type="checkbox"/> | Well Release on Active Location <input type="checkbox"/> |
| | Multi-Well Location <input type="checkbox"/> |

COGCC Comments

| Comment | User | Date |
|---|------------|------------|
| <p>COMMENT REGARDING SUBMISSION OF FORM 10:</p> <p>Collaborate with ROSEWOOD RESOURCES INC #75027 to submit the Form 10 to transfer ownership/management of the Keller Cattle Co Location #303100 to ROSEWOOD RESOURCES INC #75027</p> <p>CORRECTIVE ACTION DATE Submit Form 10 by 2/08/2019.</p> | trujilloam | 02/01/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 682504482 | Equipment photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4722938 |