

Interim Reclamation and Stormwater Inspection

January 28, 2019

Operator: BISON OIL & GAS II LLC - #10661

Location ID: 432352

Inspection Document #: 682404489

Weld County, CO

SWSW Section 16 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: State 16-7-60 /1H
Location ID: 432352



Google Earth aerial imagery taken September 7, 2013, before Interim Reclamation activities were performed illustrating the total disturbance area. COGCC Staff mapped the current production area (red-polygon) on 1/28/19. Appears the Location has been reduced in size to only reasonable areas needed for production operations per Rule 1003. Vegetation throughout the Interim areas will remain IN-PROCESS.

Inspection Photos

Location Name: State 16-7-60 /1H

Location ID: 432352



Photo 1. Photo taken from the southern entrance to Location, facing North. Photo illustrates interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas has not met Rule 1003 standards and will remain IN-PROCESS.



Photo 2. Photo taken from the northeastern Location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: State 16-7-60 /1H

Location ID: 432352



Photo 3. Photo taken from the eastern interim reclamation area, facing East. Photo illustrates desirable vegetation and the current vegetative state. Vegetation is not uniform and density is not reflective of reference area vegetation.



Photo 4. Reference photo taken east of the Location, facing North.

Inspection Photos
Location Name: State 16-7-60 /1H
Location ID: 432352



Photo 5. Photo taken from the eastern topsoil stockpile, facing West. Operator shall comply with Rule 1002.c. to ensure topsoil is protected until final reclamation activities.



Photo 6. Photo taken from the northwestern Location, facing North. Appears a fire came onto Location. Operator will be responsible for complying with Rule 1003 vegetative standards.