

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2019

Submitted Date:

02/06/2019

Document Number:

674902526

**FIELD INSPECTION FORM**

Loc ID 451044 Inspector Name: Beam, Russell On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@crestonep r.com	<a href="#">ALL INSPECTIONS</a>

**General Comment:**

This is a Construction and Stormwater Inspection in response to Form 42: Notice of construction- Document #401892699.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Operator does not appear to have implemented and maintained Best Management Practices (BMPs) to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation per Rule 1002.f.(2). Operator does not appear to have implemented BMPs in accordance with good engineering practices per Rule 1002.f.(2). Portions of the berm BMP are unconsolidated. An unconsolidated berm BMP is not a proper functioning BMP. Portions of the ditch BMP have been altered from construction operations and needs maintenance. See attached inspection photos for more details.

**Corrective Action:** Install, repair, or replace required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 02/06/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401931729	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726659">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726659</a>
674902540	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726653</a>