

APACHE CANYON 12-05 API # 05-071-06170 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100056




PHOTO 1: THE LIQUID RING COMPRESSOR SKID AND THE STAINS ON THE GROUND WERE CLEANED UP.

APACHE CANYON 12-05 API # 05-071-06170 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100056



PHOTO 2: THE LIQUID RING COMPRESSOR SKID AND THE STAINS ON THE GROUND WERE CLEANED UP.

APACHE CANYON 12-05 API # 05-071-06170 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100056



PHOTO 3: THE LIQUID RING COMPRESSOR SKID AND THE STAINS ON THE GROUND WERE CLEANED UP.

APACHE CANYON 12-05 API # 05-071-06170 - TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 DATE: FEBRUARY 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100056



PHOTO 4: THE LIQUID RING COMPRESSOR SKID AND THE STAINS ON THE GROUND WERE CLEANED UP.