

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401949451
Date Received:
02/23/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

10 of 10 CAs from the FIR responded to on this Form

10 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

HART TIMOTHY B

(303) 999-5420

thart@fremontpetroleum.com

Kosola, Jason

jason.kosola@state.co.us

Pesicka, Conor

conor.pesicka@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900420

Inspection Date: 02/15/2019

FIR Submit Date: 02/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 459837

Location Name: JW Powell Number: 23-35 County: FREMONT

Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

FACILITY - API Number: 05-043-00 Facility ID: 459836

Facility Name: JW Powell Number: 23-35

Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

CORRECTIVE ACTIONS:

1 CA# 122595

Corrective Action: "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator
Comment:

No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative:

2 CA# 122596

Corrective Action: Remove and dispose of trash debris from the location and along the access road.
Comply with Rule 603.f .

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator Comment: Further to comments made on Document ID 401949377, all trash and debris has been collected and properly disposed of properly.

COGCC Decision: _____

COGCC
Representative:

3 CA# 122597

Corrective Action: Comply with Rule 603.f .

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/22/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative:

4 CA# 122598

Corrective Action: Amend the 2A to reflect the total amount of disturbance that was created. Submittal of the amended 2A does not preclude enforcement action.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/22/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative:

5 CA# 122599

Corrective Action: Install tertiary containment along the cross and down gradient parameters of the location. Stormwater controls must be installed to good engineering practice. Install or repair required BMPs per Rule 1002.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: In order to add more clarity to comments made in Document ID 401949377, the following statement is being added.

Berms damaged by equipment moves are being repaired and properly compacted; damaged wattles are being repaired/replaced, properly trenched in, staked and overlapped. Tertiary stormwater BMPs will be installed cross and down gradient.

COGCC Decision: _____

COGCC
Representative: _____

6 CA# 122600

Corrective Action: Provide the calculations and quantitative descriptions for the amount of topsoil salvaged and stored at the location. Submit the information by 2/24/2019. Submittal of the information does not preclude enforcement action.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/23/2019

Operator Comment: Topsoil salvaged during pad construction consisted of blading the top six inches of soil from an 80 foot by 100 foot area where the drill rig and completions equipment would be located resulting in approximately 150 cubic yards of topsoil storage. AusCo intends to decompact topsoil from areas not salvaged during construction and reseed all areas not needed for production purposes.

COGCC Decision: _____

COGCC
Representative: _____

7 CA# 122601

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative: _____

8 CA# 122602

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative: _____

9 CA# 122603

Corrective Action: Properly install a compacted berm along the east side of the location. Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: _____

COGCC
Representative: _____

Corrective Action: Properly install the culvert at the stream crossing to the grade of the channel with liner and armoring rip/rap. Install adequately sized sediment traps to handle location stormwater flow. Stormwater controls must be installed in accordance to good engineering practice. Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: Operator would like to clarify comments made in Document ID 401949377 by stating that 3 - 24" culverts will be required.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has added additional comments to the existing Document ID 401949377.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron

Signed: _____

Title: Executive VP

Date: 2/23/2019 4:13:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files