

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401950501
Date Received:
02/25/2019

FIR RESOLUTION FORM

CA Summary:
10 of 10 CAs from the FIR responded to on this Form
10 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
HART TIMOTHY B	(303) 999-5420	thart@fremontpetroleum.com
Pesicka, Conor		conor.pesicka@state.co.us
Kosola, Jason		jason.kosola@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900420
Inspection Date: 02/15/2019 FIR Submit Date: 02/20/2019 FIR Status:

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC Company Number: 10412
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 459837

Location Name: JW Powell Number: 23-35 County: FREMONT
Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.348638 Longitude: -105.190784

FACILITY - API Number: 05-043-00 Facility ID: 459836

Facility Name: JW Powell Number: 23-35
Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.348638 Longitude: -105.190784

CORRECTIVE ACTIONS:

1 CA# 122595
Corrective Action: "Properly treat or dispose of oily waste in accordance with 907.e." Date: 02/15/2019
Response: CA COMPLETED Date of Completion: 02/21/2019
Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Corrective Actions Complete will be verified by an inspection.

2 CA# 122596

Corrective Action: Remove and dispose of trash debris from the location and along the access road. Comply with Rule 603.f .

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator Comment: No additional comments since 2/23/2019 FIRR data entry, Document ID 401949451.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Corrective Actions Complete will be verified by an inspection.

3 CA# 122597

Corrective Action: Comply with Rule 603.f .

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/22/2019

Operator Comment: No additional comments since 2/22/2019 FIRR data entry, Document ID 401949377.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Corrective Actions Complete will be verified by an inspection.

4 CA# 122598

Corrective Action: Amend the 2A to reflect the total amount of disturbance that was created. Submittal of the amended 2A does not preclude enforcement action.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: Operator has been in contact with several surveyors and is working to secure services in the immediate future, in order to facilitate the survey work necessary to accurately calculating the total amount of disturbance area that was created and further for the completion of the amended the Form 2A.

COGCC Decision: **Not Approved**

COGCC Representative: This is a notice and not completion of corrective action.

5 CA# 122599

Corrective Action: Install tertiary containment along the cross and down gradient parameters of the location. Stormwater controls must be installed to good engineering practice. Install or repair required BMPs per Rule 1002.f.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: Please see attached photos.

COGCC Decision: **Not Approved**

Photos do not show tertiary containment along the cross and down gradient parameters of the location.

COGCC
Representative:

6  CA# 122600

Corrective Action: Provide the calculations and quantitative descriptions for the amount of topsoil salvaged and stored at the location. Submit the information by 2/24/2019. Submittal of the information does not preclude enforcement action.

Date: _____

Response: CA COMPLETED Date of Completion: 02/23/2019

Operator Comment: No additional comments since 2/23/2019 FIRR data entry, Document ID 401949451.

COGCC Decision: **Not Approved**

COGCC Representative: This corrective action and form is being denied because operator has not provided complete information on the topsoil salvaged per corrective action. No descriptions were included. From the information provided the operator only salvaged topsoil on an area of 0.18 acre on a disturbance of 1.12 acre location.

7  CA# 122601

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED Date of Completion: 02/28/2019

Operator Comment: Please see attached photos.

COGCC Decision: **Not Approved**

COGCC Representative: The photo does not show completion of corrective action. Corrective Actions Complete will be verified by an inspection.

8  CA# 122602

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED Date of Completion: 02/28/2019

Operator Comment: Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Corrective Actions Complete will be verified by an inspection.

9  CA# 122603

Corrective Action: Properly install a compacted berm along the east side of the location. Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED Date of Completion: 02/28/2019

Operator Comment: Please see attached photos.

COGCC Decision: **Not Approved**

COGCC Representative: The photo does not show completion of corrective action. Corrective Actions Complete will be verified by an inspection.

10  CA# 122604

Corrective Action: Properly install the culvert at the stream crossing to the grade of the channel with liner and armoring rip/rap. Install adequately sized sediment traps to handle location stormwater flow. Stormwater controls must be installed in accordance to good engineering practice. Install or repair required BMPs per Rule 1002.f.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator Comment: Operator is ordering necessary materials for culvert repair. Currently completing preceding tasks, as this construction effort will limit access to the location.

No additional comments since 2/23/2019 FIRR data entry, Document ID 401949451.

COGCC Decision: **Not Approved**

COGCC Representative: It appears the sediment traps have been reconstructed.
Corrective Actions Complete will be verified by an inspection.
"Culvert" - This is a notice and not completion of corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached photos in regard to the CA's.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron J Goss

Signed: _____

Title: Executive VP

Date: 2/25/2019 3:02:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401950501	FIR RESOLUTION SUBMITTED
401950705	Example of ditch & berm compaction 01
401950708	Example of ditch & berm compaction 02
401950709	NE Sediment trap
401950710	SE Sediment trap

Total Attach: 5 Files