

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

03/01/2019

Document Number:

695100241**FIELD INSPECTION FORM**Loc ID 307873 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ash, Margaret		margaret.ash@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258678	WELL	PR	12/04/2003	GW	071-07123	LORENCITO 10-2-34-67	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN IS MISSING REQUIRED INFORMATION. NO EMERGENCY CONTACT INFORMATION POSTED.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/27/2019

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	DISCHARGING PRODUCED WATER WHILE BYPASSING SEPARATOR.		
Corrective Action:	IMMEDIATELY BEGIN TREATING PRODUCED WATER PRIOR TO DISPOSING. COMPLY WITH COGCC RULE 907. e. (2)	Date:	
Type	OTHER		
Comment:	APP. 12" BY 24" SECTION OF IMPACTED SOIL NEAR WELLHEAD. SEE LOCATION PHOTOS. REMOVE AND PROPERLY DISPOSE OF IMPACTED SOIL.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	04/01/2019
Type	OTHER		
Comment:	NO RECORDS FOR SURFACE DISCHARGE FOUND IN COGCC DATABASE.		
Corrective Action:	Provide documents listed under 907.e(2)E to Field Inspection Unit Manager with 24 hours.	Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	LAST CAL. 11/13/18		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	BREADENHEAD IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

**Venting:**

Yes/No NO

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

<b>Inspected Facilities</b>				
Facility ID: 258678	Type: WELL	API Number: 071-07123	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Environmental****Spill/Remediation:**Comment: Corrective  
Action: Date: Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100266	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750510">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750510</a>