

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2019

Submitted Date:

03/12/2019

Document Number:

688401491**FIELD INSPECTION FORM**Loc ID 320115 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 19035Name of Operator: OVERLAND RESOURCES LLCAddress: SUITE C18 PMB 440City: GREENWOOD State: CO Zip: 80121**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pandolfo, Chris	630-387-6506	admin@overlandresourcesllc.com	All Inspections
Anderson, Robert	(303) 800-6175	admin@overlandresourcesllc.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202703	WELL	SI	07/01/2017	GW	001-08108	HANDKE 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adaquate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around WH		
Corrective Action:	Comply with 603 f	Date:	10/26/2018

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	sucker rod		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 202703 Type: WELL API Number: 001-08108 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Tuesday march 12 at approximately 1201hrs, I Randy Silver,
 conducted a follow up on-site inspection at a Overland Resources location Handke #1 in
 Adams county Colorado.
 While there, I observed Production WH
 During this inspection the following possible compliance issues were observed:
 Weeds Rule 603 f CAD of 10-26-18 See photo 1.

silverr

03/12/2019

This is a follow up inspection per DOC # 688400413. All corrective actions had not been
 addressed at time of follow up inspection.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401492	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761570