

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	WH sign has wrong locaion number on sign		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/22/2018

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201510 Type: WELL API Number: 001-06913 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday March 12, 2019 at approximately 1230hrs , I Randy Silver, conducted a follow up on-site inspection at a Painted Pegasus Petroleum site Piland #1 API# 05-001-06913 in Adams county Colorado. While there, I observed a production site. During this inspection the following possible compliance issues were observed: Sign posted with incorrect information Rule 210 b CAD of 3-22-18 see photo 1. This is a follow up inspection per DOC# 677400630. At time of inspection well head sign was still incorrect. 2" pipe appeared to be removed from location. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	03/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401494	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761572