

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401970643

Date Received:

03/12/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10670

Name of Operator: MALLARD EXPLORATION LLC

Address: 1400 16TH STREET SUITE 300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
	720-543-7951	cogccinspections@mallardexploration.com
Erin Mathews	720-543-7959	emathews@mallardexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504576

Inspection Date: 03/08/2019

FIR Submit Date: 03/11/2019

FIR Status:

Inspected Operator Information:

Company Name: MALLARD EXPLORATION LLC

Company Number: 10670

Address: 1400 16TH STREET SUITE 300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 447902

Location Name: Shull Pad Number: 9-59-31-NENW County:

Qtrqtr: NENW Sec: 31 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.711378 Longitude: -104.022585

FACILITY - API Number: 05-123-00 Facility ID: 447902

Facility Name: Shull Pad Number: 9-59-31-NENW

Qtrqtr: NENW Sec: 31 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.711378 Longitude: -104.022585

CORRECTIVE ACTIIONS:

1 CA# 123113

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f.

Date: 03/08/2019

Response: CA COMPLETED

Date of Completion: 03/11/2019

Operator Comment: BMP ditches that were breached have been cleaned and re-bermed to control stormwater. Mallard Exploration is conduction additional field research regarding sizing and sufficiency of all BMPs on location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the resolution was received. It is not an acknowledgement that the corrective action has been passed. Operator has not provided any documentation showing corrective action has been addressed, a field inspection will be conducted at a future date to evaluate compliance with COGCC Rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Since Mallard Exploration acquired this location from another operator and was not involved in the pad construction, Mallard is completing an as-built survey of the location to determine if the BMPs have been designed and constructed in accordance with good engineering practice. Mallard will have a third party engineering firm review the as-built survey and provide sizing calculations. If the BMPs are found to be insufficiently sized, a site specific stormwater management plan will be submitted to the COGCC and implemented in the field.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Erin Mathews Signed: _____

Title: VP Development Date: 3/12/2019 4:36:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401970643	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files