

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401972132

Date Received:

03/14/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Gene VanDeest	307-577-5324	genev@kirkwoodcompanies.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504293

Inspection Date: 12/19/2018

FIR Submit Date: 12/20/2018

FIR Status: _____

Inspected Operator Information:

Company Name: WESCO OPERATING INC

Company Number: 95520

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

LOCATION - Location ID: 317056

Location Name: RUDNIK-63S51W Number: 27SESW County: _____

Qtrqr: SESW Sec: 27 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.758680 Longitude: -103.078950

FACILITY - API Number: 05-121- -00 Facility ID: 317056

Facility Name: RUDNIK-63S51W Number: 27SESW

Qtrqr: SESW Sec: 27 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.758680 Longitude: -103.078950

CORRECTIVE ACTIONS:

1 CA# 121215

Corrective Action: Clean/remediate or remove contaminated soils. Conduct weed management. Perform reclamation on location and access road in accordance with COGCC 1000 series rules and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 3/15/2019

Date: 03/15/2019

Response: CA COMPLETED Date of Completion: 03/12/2019

See operator comment and submittal section below. Wesco will monitor seeded area for growth during the

Operator Comment: following growing season.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Wesco has complied with all of the corrective actions listed on the field inspection form (document number 682504293). During February 25-28 (2019) and March 7-12 (2019) Wesco staff and contractors completed the following: removed approximately 24 cubic yards of contaminated soil from the site facility and hauled material to Buffalo Ridge Landfill, addressed the weeds on site, removed the power poles, reclaimed additional portions of the facility road, recontoured the facility and road, added manure for fertilization and seeded the site facility using NRCS suggested seed mix, and crimped straw on seeded area to enhance seed stabilization. Waste disposal manifests will be submitted when available.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gene VanDeest

Signed: _____

Title: HSE Coordinator

Date: 3/14/2019 2:46:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401972132	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files