

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401938411  
Date Received:  
02/13/2019

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 792 BUCKHORN DR  
City: RIFLE State: CO Zip: 81650  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>McRickard, Chris</u>		<u>cmcrickard@ursaresources.com</u>
<u>Knudson, Dwayne</u>	<u>970-456-3335</u>	<u>dknudson@ursaresources.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 681701162  
Inspection Date: 01/11/2019 FIR Submit Date: 01/14/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC Company Number: 10447  
Address: 1600 BROADWAY ST STE 2600  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 335879

Location Name: BOIES-62S98W Number: 28SESE County: \_\_\_\_\_  
Qtrqr: SESE Sec: 28 Twp: 2S Range: 98W Meridian: 6  
Latitude: 39.840473 Longitude: -108.394358

### FACILITY - API Number: 05-103- -00 Facility ID: 335879

Facility Name: BOIES-62S98W Number: 28SESE  
Qtrqr: SESE Sec: 28 Twp: 2S Range: 98W Meridian: 6  
Latitude: 39.840473 Longitude: -108.394358

### CORRECTIVE ACTIONS:

1 ☒ CA# 121690

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). (condensate AST)

Date: 02/14/2019

Response: CA COMPLETED

Date of Completion: 02/12/2019

Operator Comment: Repairs completed. See photos

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2 ☒ CA# 121691

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). (90 bbl produced water AST)

Date: 02/14/2019

Response: CA COMPLETED

Date of Completion: 02/12/2019

Operator  
Comment: Repairs completed. See photos.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please send to Steven Arauza

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dwayne Knudson

Signed: \_\_\_\_\_

Title: Environmental Manager

Date: 2/13/2019 10:45:18 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401938411	FIR RESOLUTION SUBMITTED
401938432	Liner Repair
401938433	Liner Repair

Total Attach: 3 Files