

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2019

Submitted Date:

03/29/2019

Document Number:

675002098**FIELD INSPECTION FORM**
 Loc ID 312598 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	GW	077-08594	SOUTH SHALE RIDGE 1-14	SI

General Comment:

This is a follow up inspection to FIR Doc#689401338 and 675001728 Any corrective actions not addressed from previous inspections are still applicable.

This well is not part of Order 1V-609.

No corrective action have been made at this time.

Location			
Lease Road:			
Type	Access		
comment:	See comments in Storm water		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No wellhead sign present		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 03/11/2019
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-858-8550 911 and Nearest Access Posted		
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	weeds (debris) are still present in tank containment and on berm. Vegetation is now surrounding wellhead and equipment. Original corrective action and date still apply.		
Corrective Action:	Remove to comply with 603.f.		Date: 04/29/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Horizontal Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	

Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	See Housekeeping					
Corrective Action:					Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	221992	Type:	WELL	API Number:	077-08594	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Well last produced in April 2010. MIT Doc #400797407 2-11-15</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Stormwater erosion not being controlled on the location at this time. BMP's not in place or maintained. Heavy erosion and tranferance of sediment onto and off location.						Date: 04/29/2019
Corrective Action: Install or repair required BMPs per Rule 1002.f.						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002102	Inspection 675002098 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778914