



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers Missing volume sign		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/25/2019
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign or label not posted or information inaccurate on tanks or containers Produced water tank missing placars		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/25/2019

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil under load out line from crude oil tank		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	04/25/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239942 Type: WELL API Number: 123-07730 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>            On Monday March 25, 2019 at approximately 1826 hrs, I Randy Silver conducted an on-site inspection at a KP Kuffmin Company site Dechant State #1 in Weld Colorado.            While there, I observed Production Well.            During this inspection the following possible compliance issues were observed:            Sign or placard not posted: rule 210 d Corrective action date of 4-25-19 See photo 5            Stained soil: Rule 907 e Corrective action date of 4-25-19 See photos 2            A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.            This is a summary of inspection report.</p>	silverr	03/25/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401984551	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773487</a>
688401651	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773481</a>