

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/01/2019

Submitted Date:

04/01/2019

Document Number:

695100399

FIELD INSPECTION FORM
 Loc ID 309434 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10084

Name of Operator: PIONEER NATURAL RESOURCES USA INC

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295001	WELL	PR	07/31/2008	GW	071-09529	ZUESS FEDERAL 11-10	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	WELL SIGN IS LAYING ON LOCATION NEAR METER RUN.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	IMPACTED SOIL ON NORTH SIDE NEAR ENGINE SKID. IMPACTED SOIL NEAR BACK (SOUTHEAST) SIDE OF ENGINE SKID		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: <u>05/01/2019</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	NORTHEAST ANCHOR MARKER IS DOWN		
Corrective Action:	Mark guy line anchors per Rule 1003. a.		Date: <u>04/16/2019</u>
Type: Progressive Cavity	# 1		
Comment:	PACKING IS SPRAYING PRODUCED WATER OUT ON LOCATION.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>04/02/2019</u>
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 295001 Type: WELL API Number: 071-09529 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100400	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780752