

FORM
22

Rev
06/18

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:
04/10/2019

Accident Tracking No.:
401994094

ACCIDENT REPORT

As required by Rule 602.d.

CONTACT INFORMATION

☐ Initial Notice of Accident ☒ Subsequent Notice of Accident

OGCC Operator Number: 10459 Contact Name: Jeff Rickard
Name of Operator: EXTRACTION OIL & GAS INC Phone: (720) 737-5144
Address: 370 17TH STREET SUITE 5300 Fax: ()
City: DENVER State: CO Zip: 80202 Email: jrickard@extractionog.com

ACCIDENT DATE, TIME, and LOCATION (Please be as specific as possible)

Date of Accident: 02/08/2019 Time of Accident: 9:00 AM
API Number: 05- Facility ID: 439204 Type of Facility: LOCATION
Well/Facility Name: WAAG SOUTH SESW Well/Facility Num: PAD #1
County: WELD
Location: QTRQTR: SESW Sec: 19 Twp: 7N Rng: 65W Meridian: 6
Lat: 40.554470 Long: -104.707150
Field Name: EATON Field Number: 19350

Was there a reportable E & P waste spill or release associated with this accident? Yes ☐ No ☒
If YES, enter the Document Number of the Initial Spill/Release Report, Form 19: _____
Was there a Grade 1 Gas Leak associated with this accident? Yes ☐ No ☒
If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report, Form 44: _____

DESCRIPTION OF ACCIDENT

Number of members of the general public injured: 0
Number of workers injured: 0
Number of general public fatalities: 0
Number of worker fatalities: 0

Type of Accident (check all that apply):

☒ Fire
☐ Explosion
☐ Detonation
☐ Uncontrolled Release
☐ Other Description: _____

Detailed Description of Accident:

- Do not include names of injured, injuries, or medical treatment information.
- Subsequent Report must include Root Cause.

The root cause of the incident was determined to be a pin hole from a material defect in the fire tube of the separator.

Extraction has a rigorous separator maintenance program that includes cleaning, cathodic protection and anti-corrosion chemical treatments. To further investigate additional potentials related to this incident, Extraction dismantled and inspected all separators of the same contemporary group as the separator involved in the incident. In the inspection of all the "like in kind" separators, Extraction made precautionary repairs to a total of 4 fire tubes. No other issues were observed in the inspection(s).

OTHER NOTIFICATIONS

List all parties and agencies that were notified or responded to the accident. (For example: Local Government Designee, Municipality, County, BLM, EPA, CDOT, Local Emergency Planning Coordinator, etc.)

Date	Agency	Contact	Response

OPERATOR COMMENTS and SUBMITTAL

--

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Jeff Rickard

Email: jrickard@extractionog.com

Signature: _____

Title: Regulatory Compliance Co

Date: 04/10/2019

CONDITIONS OF APPROVAL, IF ANY:**COA Type****Description**

--	--

Attachment Check List**Att Doc Num****Name**

--	--

Total Attach: 0 Files

<u>General Comments</u>		
<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval
Total: 0 comment(s)		

]