

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

688401831

FIELD INSPECTION FORM

Loc ID 308859 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283710	WELL	PR	03/09/2006	GW	071-08734	GOLDEN EAGLE 20-3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location sign. Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	05/11/2019

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around HYD motor skid		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907	Date:	05/11/2019
Type	OTHER		
Comment:	Stained soil under drain line for separator		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907.	Date:	05/11/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	05/02/2019
Type: Prime Mover	# 1		
Comment:	Gas powered HYD motor		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	#		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283710 Type: WELL API Number: 071-08734 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday April 11, 2019 at approximately 1735 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site GE #20-03, at API # 05-071-08734 in Las Animas County Colorado.</p> <p>While there, I observed a production well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Un legible and faded location sign: Rule 210 e Corrective action date of 5-11-19 See photo 1</p> <p>Stained soil Rule 907 e Corrective action date of 5-11-19 See photo 2</p> <p>Stained soil; Rule 907 Corrective action date of 5-11-19 See photos 4,5</p> <p>Guy line anchors; Rule 1003 a Corrective action date of 5-2-19 See photos 7,8</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401832	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792650