

# Inspection Photos

API: 05-071-06409

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/12/2019

## Inspection Photos



**Photo 1.** Facing toward the location. Rock rip/rap has been placed diversion ditches. Slope has been reseeded.