

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402003890

Date Received:

04/15/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fischer, Alex

alex.fischer@state.co.us

Waldron, Emily

emily.waldron@state.co.us

Spence Laird

slaird@sandridgeenergy.com

Matt Church

mchurch@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 694500085

Inspection Date: 03/26/2019

FIR Submit Date: 04/04/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: _____

Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057- -00 Facility ID: 447512

Facility Name: Open Range Number: 18

Qtrqtr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 CA# 123868

Corrective Action: A FIRr should be filed regarding the status of compliance with COGCC rule 605.a(4) was a synthetic or engineered liner installed under the tank, see photo #10 and #11.

Date: 05/04/2019

Response: CA COMPLETED

Date of Completion: 04/09/2019

Liner installed under tank and inside secondary containment berm on 4/9/2019.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 123869

Corrective Action: liner should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907.A.

Date: 04/06/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator
Comment:

Liner removed and hauled to disposal.

COGCC Decision:

COGCC
Representative:

3 CA# 123870

Corrective Action: soil should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907.

Date: 04/06/2019

Response: CA COMPLETED

Date of Completion: 04/05/2019

Operator
Comment:

Soil removed from site

COGCC Decision:

COGCC
Representative:

4 CA# 123871

Corrective Action: Fluid and soil should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907.

Date: 04/06/2019

Response: CA COMPLETED

Date of Completion: 04/05/2019

Operator
Comment:

Site was bladed and staining removed with hydro vac.

COGCC Decision:

COGCC
Representative:

5 CA# 123872

Corrective Action: Spilled fluid and soil should be removed in 48 hrs (per COGCC Corrective Action matrix) and handled per COGCC rule 907.

Date: 04/06/2019

Response: CA COMPLETED

Date of Completion: 04/05/2019

Operator
Comment:

Site was bladed and staining was removed with hydro vac

COGCC Decision:

COGCC
Representative:

6 CA# 123873

Corrective Action: COGCC rule 1002.f and Sandridge stormwater permit conditions should be met and maintained. COGCC corrective action matrix states that immediate response is required for locations under construction.

Date: 04/04/2019

Response: CA COMPLETED

Date of Completion: 04/04/2019

Operator
Comment:

Standing water was removed from site with bobtail and hydro vac trucks.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed:

Title: EH&S Specialist

Date: 4/15/2019 9:53:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402003891	Tank Liner Installed
-----------	----------------------

Total Attach: 1 Files