

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: THERE IS APP. 3' BY 2' AREA OF IMPACTED SOIL OUTSIDE THE NORTHWEST CORNER OF COMPRESSOR SKID. PHOTO 4: COMPRESSOR SKID IS FULL OF OILY WATER AND IS RUNNING OUT OF CONTAINMENT IMPACTING THE SOIL ON NORTHEAST SIDE OF COMPRESSOR SKID.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	05/12/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Compressor	# 1		
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	Provide COGCC with documentaton showing approval of use of vacuum pump.	Date:	05/02/2019
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 262539 Type: WELL API Number: 071-07557 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100501	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795126