

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	05/16/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipmet; 2' piping from well to flow line parts disconnected and laying on ground.		
Corrective Action:	Comply with 603 f	Date:	05/16/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 412020 Type: WELL API Number: 123-30358 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: At time of inspection 2' piping from well head to flow line has been disconnected and laying on ground.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday April 16, 2019 at approximately 1549 hrs , I Randy Silver conducted an on-site inspection at KerrMcGee site Sawdey #22-30, at API# 05-12330355 in Weld County Colorado.</p> <p>While there, I observed a Production well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment; Rule 603 f Corrective action date of 5-16-19 See photo 2</p> <p>Unused, unmarked not LOTO riser; Rule 603 f Corrective action date of 5-16-19 See photo 2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401902	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4798017