



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash blocking road next to crude oil tank		
Corrective Action:	Comply with 603 f	Date:	05/07/2019
Type	OTHER		
Comment:	Stained soil under crude oil load line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	05/23/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	Square tubing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Square tubing		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 206607 Type: WELL API Number: 013-06102 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday April 23, 2019 at approximately 1010 hrs, I Randy Silver, Conducted an on-site inspection at a Extraction oil and gas site Tyler #1-4, at API# 05-013-06102 in Bolder County Colorado.                      While there, I observed a producing well site.                      During this inspection, the following possible compliance issues were observed:                      Trash: Rule 603 f Corrective action date of 5-7-19 See photo 4                      Stained soil: Rule 907 e Corrective action date of 5-23-19 See photo 6                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	04/23/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401961	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4804153">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4804153</a>