

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401971611  
Date Received:  
03/13/2019

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Labowskie, Steve		steve.labowskie@state.co.us
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com
Inspections, All		SanJuanCOGCC@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 687903889  
Inspection Date: 03/11/2019 FIR Submit Date: 03/11/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 311971

Location Name: COGBURN GAS UNIT A-M34N8W Number: 24NENE County: LA PLATA  
Qtrqtr: NENE Sec: 24 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.181062 Longitude: -107.663521

### FACILITY - API Number: 05-067- -00 Facility ID: 288738

Facility Name: COGBURN A Number: 4  
Qtrqtr: NENE Sec: 24 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.181062 Longitude: -107.663521

### CORRECTIVE ACTIONS:

1 ☒ CA# 123111

Corrective Action: Please comply with Rule 605.d. Date: 03/13/2019

Response: CA COMPLETED Date of Completion: 03/11/2019

Operator Comment: The evening of March 11, 2019 a lead operations technician was dispatched to location to check the coffin box leak reported in the inspection. Upon arrival he check the packing and performed maintenance on the packing and the coffin box. The maintenance included tightening everything upon the equipment. He observed for an

hour and no leaking was observed. The same technician returned to location the following day to ensure that the maintenance had resolved the issue and found the equipment to be functioning correctly and no leak occurring. BPX has addressed this issue.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The evening of March 11, 2019 a lead operations technician was dispatched to location to check the coffin box leak reported in the inspection. Upon arrival he check the packing and performed maintenance on the packing and the coffin box. The maintenance included tightening everything upon the equipment. He observed for an hour and no leaking was observed. The same technician returned to location the following day to ensure that the maintenance had resolved the issue and found the equipment to be functioning correctly and no leak occurring. BPX has addressed this issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 3/13/2019 4:34:20 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401971611	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files