

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

688402016

**FIELD INSPECTION FORM**

Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extractionog.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463343	WELL	DG	03/28/2019		014-20845	Interchange B N35-20-1N	DG

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Sound walls		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 463343 Type: WELL API Number: 014-20845 Status: DG Insp. Status: DG

**Complaint**

Comment: Field Inspector Assigned: Randy Silver

Complaint Received  
Date: 04-22-2019

Complaint Contacted:  
Date: 04-24-2019 Time: 11:52 AM by Phone

Facility ID #: 456747  
Inspection Document # 688401998

Nature of Complaint: Odor

Field Inspector Actions:  
On 04-23-2019, I was contacted be COGCC staff in reference to some complaint received be the COGCC in reference to Odor. The complaint stated At approximately 9:45 pm she drove on 156th to Huron near the Interchange Pad (facility ID 456747). There was a strong smell of oil. As I arrived home at 156th and Quivas the odor was overpowering. My husband who does not have a very sensitive nose went outside and was overcome by the odor as well. This has an impact on my ability to breathe. I utilized me inhaler after coming into the house. The wind was light out of the east tonight at around 1-2mph according to my weather app. Is it possible that the odor is from the loads of trucks that transport the drill cutting? Could it be from the heated mud as it comes to the surface? Are they utilizing any sort of chiller system on the mud when it comes up? There have been multiple reports to Broomfield today about strong oil odor smells. They dissipate then return.

On 04-24-2019, I attempted to make contact with the complaint who indicated she was smelling oil like odor coming from the Interchange A&B location. I informed her they are using a chiller system. I spoke with Danny Herrera Rig supervisor on site and he informed me they had not been hauling drilling cutting at night, not to say they will not if needed. He also stated that they are using a deodorant to treat the cuttings to reduce odor. I informed her the next time this happens to file another complaint and to contact me and I would come out and perform another onsite inspection to try to fine the source of the odor. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I drove to complainants address and did not smell any unusual odors. I did not smell any unusual odors at the Interchange B pad. Complainant also had concern that the odor might be coming from another well close to her house that was in the P&A process. At time of inspection at the Nordstrom 3-9 Doc #688401996, I did not smell any unusual odors.

See inspection document #688401998 per my inspection.  
All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
Inspection due to complaint. Inspection doc#688401998	silverr	04/24/2019